



MU106A

1 pole, MU, Curve C, 6kA

Description	P.U.	Cat ref.
MCB 1P 6kA C-6A 1M	12	MU106A
MCB 1P 6kA C-10A 1M	12	MU110A
MCB 1P 6kA C-16A 1M	12	MU116A
MCB 1P 6kA C-20A 1M	12	MU120A
MCB 1P 6kA C-25A 1M	12	MU125A
MCB 1P 6kA C-32A 1M	12	MU132A
MCB 1P 6kA C-40A 1M	12	MU140A
MCB 1P 6kA C-50A 1M	12	MU150A
MCB 1P 6kA C-63A 1M	12	MU163A



MU206A

2 pole, MU, Curve C, 6kA

Description	P.U.	Cat ref.
MCB 2P 6kA C-6A 2M	6	MU206A
MCB 2P 6kA C-10A 2M	6	MU210A
MCB 2P 6kA C-16A 2M	6	MU216A
MCB 2P 6kA C-20A 2M	6	MU220A
MCB 2P 6kA C-25A 2M	6	MU225A
MCB 2P 6kA C-32A 2M	6	MU232A
MCB 2P 6kA C-40A 2M	6	MU240A
MCB 2P 6kA C-50A 2M	6	MU250A
MCB 2P 6kA C-63A 2M	6	MU263A



MU306A

3 pole, MU, Curve C, 6kA

Description	P.U.	Cat ref.
MCB 3P 6kA C-6A 3M	4	MU306A
MCB 3P 6kA C-10A 3M	4	MU310A
MCB 3P 6kA C-16A 3M	4	MU316A
MCB 3P 6kA C-20A 3M	4	MU320A
MCB 3P 6kA C-25A 3M	4	MU325A
MCB 3P 6kA C-32A 3M	4	MU332A
MCB 3P 6kA C-40A 3M	4	MU340A
MCB 3P 6kA C-50A 3M	4	MU350A
MCB 3P 6kA C-63A 3M	4	MU363A



MU420A

4 pole, MU, Curve C, 6kA

Description	P.U.	Cat ref.
MCB 4P 6kA C-6A 4M	3	MU406A
MCB 4P 6kA C-10A 4M	3	MU410A
MCB 4P 6kA C-16A 4M	3	MU416A
MCB 4P 6kA C-20A 4M	3	MU420A
MCB 4P 6kA C-25A 4M	3	MU425A
MCB 4P 6kA C-32A 4M	3	MU432A
MCB 4P 6kA C-40A 4M	3	MU440A
MCB 4P 6kA C-50A 4M	3	MU450A
MCB 4P 6kA C-63A 4M	3	MU463A



MT106A

1 pole, MT, Curve B, 6kA

Description	P.U.	Cat ref.
MCB 1P 6kA B-6A 1M	12	MT106A
MCB 1P 6kA B-10A 1M	12	MT110A
MCB 1P 6kA B-16A 1M	12	MT116A
MCB 1P 6kA B-20A 1M	12	MT120A
MCB 1P 6kA B-25A 1M	12	MT125A
MCB 1P 6kA B-32A 1M	12	MT132A
MCB 1P 6kA B-40A 1M	12	MT140A



2 pole, MT, Curve B, 6kA

Description	P.U.	Cat ref.
MCB 2P 6kA B-6A 2M	6	MT206A
MCB 2P 6kA B-10A 2M	6	MT210A
MCB 2P 6kA B-16A 2M	6	MT216A

MT210A